

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/08/2020

Submitted Date:

01/08/2020

Document Number:

687400746**FIELD INSPECTION FORM**Loc ID 441824 Inspector Name: Huck, Keith On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1001 17TH STREET #2000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**17 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		nsvendsen@gwp.com	
		mpfister@gwp.com	
		cogccinspections@gwogco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
441825	WELL	PR	03/09/2016	OW	001-09847	Anderson 19-1-10HC	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unmarked riser near ECDs. See picture#13		
Corrective Action:	Comply with Rule 603.f .	Date:	02/10/2020
Type	UNUSED EQUIPMENT		
Comment:	Unused chemical tank. See picture#5		
Corrective Action:	Comply with Rule 603.f .	Date:	04/07/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Chainlink		
Corrective Action:		Date:	

Equipment:			corrective date
Type: LACT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	1 Automation RTU 2 Electrical Boxes		

Corrective Action:		Date:	
Type: Emission Control Device	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:	Full bucket under northern separator. See picture#14		
Corrective Action:	Location is within a designated setback location, remove trash or debris per Rule 604.c. (2)P.	Date:	01/23/2020
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: VRT	# 2		
Comment:	The east VRT is leaking from the PRV. See picture#10&11		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	01/09/2020
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: VRU	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	STEEL AST		,
Comment:	Westside tank#2 backside has a balon valve leaking. See picture#12				
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.				Date: 01/09/2020

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Inspector Name: Huck, Keith

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Shares berm with production tank				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	6	400 BBLs	STEEL AST		39.959721,-104.823517
Comment:	On all loadout buckets the bullplugs are missing on the loadout valves. Also one bucket is full of oil. See picture#8&9				
Corrective Action:	Location is within a designated setback location, bullplug or cap all loadlines per Rule 604.c.(2)O.				Date: 01/13/2020

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
	Date:			

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 441825 Type: WELL API Number: 001-09847 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadComment: Bradenhead appears to be plumbed to surface

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday, 01/08/2020 at approximately 13:27, I, Inspector Keith Huck, conducted an on-site inspection at Anderson 19-1-10HC Great Western, at Location#441824 in Adams County, Colorado.</p> <p>While there, I observed Production.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused Equipment. Remove. Rule 603f, 04/17/2020. See picture#5</p> <p>Bullplugs missing on loadout valves. Install bullplugs. 01/13/2020 Rule 604c.(2)O See Picture#8&9</p> <p>VRT Leaking from PRV. Fix. 01/09/2020 Rule 605d. See Picture#10&11</p> <p>Balon leaking on backside of water tank#2. Fix 01/09/2020 Rule 605d. See Picture#12</p> <p>Unmarked Riser. LOTO/Remove or mark for future use. 24hrs to LOTO or mark for future use. Rule 603 f. See Picture#13</p> <p>Full Bucket near north separator. Remove. 1/23/2020 Rule 604c(2)P. See picture #14</p> <p>I spoke with Natalie Svendsen and Miracle Phister with Great Western. All corrective actions were discussed.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	huckk	01/08/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687400747	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5031101