

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/09/2020

Submitted Date:

01/10/2020

Document Number:

696101831**FIELD INSPECTION FORM**Loc ID 331395 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261511	WELL	TA	04/01/2019	OW	123-20613	STATE PETERSON 22-16	PA

General Comment:This is a **PLUGGED & ABANDONED WELL / ABANDONED BATTERY** inspection.

Well(s): 1: Plugged & Abandoned | PA.

Battery: Abandoned. ALL equipment has been removed.

Reclamation progressing.

Abandoned Battery SE corner GPS coordinates: 40.403069, -104.446203

Abandoned Centralized Battery formerly served this Location ID (331395).

(Well(s): 1: Plugged & Abandoned | PA).

Reclamation progressing at PA wellsite & Abandoned Battery site.

Abandoned Centralized Battery formerly served 3 other Location IDs (331469, 331454, 331460).

(Well(s): 3: Plugged & Abandoned | PA).

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Pig Station

0

Comment: [Plugged & Abandoned | PA. ALL equipment removed.](#)Corrective Action: Date:

Type: Plunger Lift

0

Comment: [Plugged & Abandoned | PA. ALL equipment removed.](#)Corrective Action: Date:

Type: Emission Control Device

0

Comment: [Plugged & Abandoned | PA. ALL equipment removed.](#)Corrective Action: Date:

Type: Horizontal Heated Separator

0

Comment: [Plugged & Abandoned | PA. ALL equipment removed.](#)Corrective Action: Date:

Type: Bradenhead

0

Comment: [Plugged & Abandoned | PA. ALL equipment removed.](#)Corrective Action: Date:

Type: Gas Meter Run

0

Comment: [Plugged & Abandoned | PA. ALL equipment removed.](#)Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment: Plugged & Abandoned PA. ALL equipment removed.					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

PaintCondition: Other (Content) Other (Capacity)

Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0					
Comment: Plugged & Abandoned PA. ALL equipment removed.						
Corrective Action:						Date:
Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No						
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	261511	Type:	WELL	API Number:	123-20613	Status:	TA	Insp. Status:	PA
Workover									
Comment:	<div>Plugged & Abandoned PA. Well appears to be cut / capped. Form 6 doc. #402062664 indicates plugging date: 05/08/2019. Approval Pending. Reclamation progressing.</div>								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Mulching		Mulching				

Comment: [Reclamation progressing.](#)
[Mulching at Abandoned well & battery sites.](#)

Corrective Action: Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 01/09/2020 at approximately 15:33 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: PDC ENERGY INC Location Name: STATE PETERSON-65N63W /16SENW Location ID: 331395 Well Name: State Peterson 22-16 API: 05-123-20613 Location County: Weld County, Colorado Weather: Partly cloudy w/ partial snow coverage from prior storm. While there, I observed:</p> <p>Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment has been removed. Reclamation progressing. Abandoned Battery SE corner GPS coordinates: 40.403069, -104.446203</p> <p>Abandoned Centralized Battery formerly served this Location ID (331395). (Well(s): 1: Plugged & Abandoned PA). Reclamation progressing at PA wellsite & Abandoned Battery site.</p> <p>Abandoned Centralized Battery formerly served 3 other Location IDs (331469, 331454, 331460). (Well(s): 3: Plugged & Abandoned PA).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	01/10/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101832	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5033547