

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/08/2020

Submitted Date:

01/13/2020

Document Number:

690101680

FIELD INSPECTION FORMLoc ID 324565 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10467

Name of Operator: TABULA RASA ENERGY LLC

Address: 12012 WICKCHESTER LANE #660

City: HOUSTON State: TX Zip: 77079

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beardslee, Tom		tom.beardslee@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Mason, Jeremiah	719-742-6900/719-989-8469	jmason@tabularasa.com	
Meeks, Lauren		lmeeks@tabularasa.com	
Whittington, Ellice		ellice.whittington@state.co.us	
Sutherland, Bob		bobs@tabularasa.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265121	WELL	SI	04/01/2019	GW	055-06285	CADDELL 1	EG
435037	WELL	SI	04/01/2019	GW	055-06312	Caddell 2	EG
439694	WELL	PR	05/12/2016	LO	055-06319	Caddell 3	EG

General Comment:

COGCC Engineering Integrity Inspection; Flowline Inspection Only. The Corrective Actions identified during this field inspection are located in the flowline section of report. Photos uploaded can be accessed via link(s) at end of report.

Inspected Facilities

Facility ID: <u>265121</u>	Type: <u>WELL</u>	API Number: <u>055-06285</u>	Status: <u>SI</u>	Insp. Status: <u>EG</u>
Facility ID: <u>435037</u>	Type: <u>WELL</u>	API Number: <u>055-06312</u>	Status: <u>SI</u>	Insp. Status: <u>EG</u>
Facility ID: <u>439694</u>	Type: <u>WELL</u>	API Number: <u>055-06319</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>

Flowline

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: Material:
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Off location flowlines for the Caddell 1, 2 & 3 wells have not been registered with COGCC; Alignment of off location flowlines indeterminate at this time. La Veta gas plant (Facility ID #412177) located approximately 4940' to SW on the NW side of CR 441. Operator has not submitted COGCC Form 44 off location flowline registration forms.

Note: Operator has not registered any off location flowlines with COGCC; The Corrective Action outlined is applicable to all wells operated by Tabula Rasa Energy LLC with off location flowlines.

Corrective Action: **Comply with the following COGCC rule (partial description of rule):**

1101.a. Off-Location Flowline Registration. (1) An operator must register an off-location flowline constructed on or after May 1, 2018, by submitting a Flowline Report, Form 44, to the Director within 30 days after the flowline is placed into service. An off location flowline in existence prior to May 1, 2018, must be registered by October 31, 2019.

Date: 10/31/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101681	View of Caddell 1, 2 & 3 wells (looking NW)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5035640
690101682	Caddell #2 wellhead; signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5035641
690101683	Flowline risers/ valves on location (view NW)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5035642
690101684	Aerial Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5035643