

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/13/2020

Submitted Date:

01/13/2020

Document Number:

690004951

### FIELD INSPECTION FORM

Loc ID 417888 Inspector Name: Carlile, Craig On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name  | Phone | Email                         | Comment                         |
|---------------|-------|-------------------------------|---------------------------------|
| , Inspections |       | COGCCinspections@Anadarko.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 417897      | WELL | SI     | 02/01/2019  | OW         | 123-31770 | MOSER H28-30  | SI          |

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

|                    |          |  |       |
|--------------------|----------|--|-------|
| Type               | WELLHEAD |  |       |
| Comment:           |          |  |       |
| Corrective Action: |          |  | Date: |

**Emergency Contact Number:**

|                    |  |  |             |
|--------------------|--|--|-------------|
| Comment:           |  |  |             |
| Corrective Action: |  |  | Date: _____ |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Fencing/:**

|                    |          |  |       |
|--------------------|----------|--|-------|
| Type               | WELLHEAD |  |       |
| Comment:           |          |  |       |
| Corrective Action: |          |  | Date: |

**Equipment:**

|                    |     |  |                 |
|--------------------|-----|--|-----------------|
|                    |     |  | corrective date |
| Type: Plunger Lift | # 1 |  |                 |
| Comment:           |     |  |                 |
| Corrective Action: |     |  | Date:           |

**Tanks and Berms:**

| Contents           | # | Capacity | Type                | Tank ID | SE GPS |
|--------------------|---|----------|---------------------|---------|--------|
|                    |   |          | CENTRALIZED BATTERY |         | ,      |
| Comment:           |   |          |                     |         |        |
| Corrective Action: |   |          |                     |         | Date:  |

**Paint**

|                  |  |  |  |
|------------------|--|--|--|
| Condition        |  |  |  |
| Other (Content)  |  |  |  |
| Other (Capacity) |  |  |  |
| Other (Type)     |  |  |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 417897 Type: WELL API Number: 123-31770 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Shut in and locked out at flow line connection to flow line

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment  | User     | Date       |
|--|----------|------------|
| <a href="#">Routine inspection. Well is tagged that it is planned for plugging</a> | carlilec | 01/13/2020 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 690004952    | Photos      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5036008">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5036008</a> |