

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/07/2020

Submitted Date:

01/07/2020

Document Number:

679602130**FIELD INSPECTION FORM**Loc ID 438495 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10261Name of Operator: BAYSWATER EXPLORATION & PRODUCTION LLCAddress: 730 17TH ST STE 500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**16 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		wellinspections@bayswater.us	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438486	WELL	PR	08/01/2017	OW	123-40014	SRC Geis T-15-22NHZ	PR
438487	WELL	PR	03/13/2016	OW	123-40015	SRC Gies 34-15-22NHZ	PR
438488	WELL	PR	12/08/2015	OW	123-40016	SRC Gies 34-15-22NCHZ	PR
438489	WELL	PR	07/05/2017	OW	123-40017	SRC Gies T-15-22CHZ	PR
438490	WELL	PR	05/01/2017	OW	123-40018	SRC Gies D-15-22NHZ	PR
438491	WELL	PR	07/05/2017	OW	123-40019	SRC Gies 44-15-22CHZ	PR
438492	WELL	PR	12/08/2015	OW	123-40020	SRC Gies 44-15-22NHZ	PR
438494	WELL	PR	07/01/2015	OW	123-40022	SRC Gies D-15-22NCHZ	PR
446331	TANK BATTERY	AC	06/24/2016		-	SRC Gies Pad	AC

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	H2O tanks missing BBLs. See attached photo.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	02/07/2020
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment near wellheads. See attached photos.		
Corrective Action:	Comply with Rule 603.f.	Date:	01/14/2020

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:			
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Type: Emission Control Device	# 4	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 7	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 7	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 14	
Comment:		
Corrective Action:		Date:
Type: Compressor	# 2	
Comment:		
Corrective Action:		Date:
Type: Vertical Heater Treater	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 8	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	UNKNOWN
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with other tanks.				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	10	500 BBLs	STEEL AST		40.567600,-104.644700
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	438486	Type:	WELL	API Number:	123-40014	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	438487	Type:	WELL	API Number:	123-40015	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	438488	Type:	WELL	API Number:	123-40016	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	438489	Type:	WELL	API Number:	123-40017	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	438490	Type:	WELL	API Number:	123-40018	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	438491	Type:	WELL	API Number:	123-40019	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	438492	Type:	WELL	API Number:	123-40020	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	438494	Type:	WELL	API Number:	123-40022	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			

Facility ID:	446331	Type:	TANK	API Number:	-	Status:	AC	Insp. Status:	AC
--------------	--------	-------	------	-------------	---	---------	----	---------------	----

Producing Well

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p><b>**Weather Conditions:</b> Sunny, muddy/snow on ground</p> <p>On Tuesday, January 7, 2020 at approximately 15:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at SRC GIES PAD (Bayswater Exploration &amp; Production), at location #: 438495 in WELD COUNTY Colorado.</p> <p>While there, I observed a producing facility.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1. Two H2O tanks do not have BBLS labeled. INSTALL SIGN TO COMPLY WITH RULE 210.B. (Corrective Action Date: February 7, 2020) See attached photo #3.</p> <p>2. Unused equipment (Appears to be empty methanol barrels) near wellheads. PLEASE REMOVE TO COMPLY WITH RULE 603.F. (Corrective Action Date: January 14, 2020) See attached photos #6, 8, 18.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	santistb	01/07/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402279662	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5030692">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5030692</a>
679602131	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5030689">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5030689</a>