

Inspected Facilities

Facility ID: 217854 Type: WELL API Number: 071-06633 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 119942 Lat: 37.100801 Long: -104.756573

Reference Point: SE Other: _____ Length: 130 Width: 120

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: NO

Comment: **PHOTO 3: PRODUCED WATER LEVEL IS ABOVE THE 2' FREEBOARD MARKER (SPOKE WITH DAVE GARCIA WITH EVERGREEN BY PHONE @ APP. 11:02 1-7-20).**

Corrective Action

LOWER FLUID LEVEL IN PIT TO MAINTAIN AT LEAST 2' OF FREEBOARD PER RULE 902.b.

Date: 01/08/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402279733	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5030801
695101959	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5030788