

Inspection Photos

Operator: Logos Operating
Location/API #: 067-08119
Date: 1-9-2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southeastern well road facing westward. Dense Russian thistle debris observed throughout the project area. Perennial grasses such as sand dropseed is present in patches.



Photo 3. View of the eastern project area from the southeastern edge of the working area facing northward. Dense Russian thistle debris is present.



Photo 4. View of the western project area from the southwestern corner facing northward. Area is largely snow covered.



Photo 5. View of musk thistles within the western project area. Approximately 100 individuals observed.



Photo 6. View of area (in yellow box) that appears needed for production operations. Disturbance areas outside of yellow box (other than active roads) need reclamation per the 1003 reclamation rules.



Photo 7. View of reference area, comprised of sagebrush shrubland.