

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/14/2020

Submitted Date:

01/14/2020

Document Number:

689803597**FIELD INSPECTION FORM**Loc ID 311768 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 7125Name of Operator: BEEMAN OIL & GAS LLCAddress: 3401 QUEBEC ST SUITE 9105City: DENVER State: CO Zip: 80207**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Stepp, Sarah		wccassistant@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223110	WELL	PR	06/25/1997	OW	081-06472	ELK SPRINGS UNIT 3	PR

General Comment:[COGCC Inspection Report 689803597 Summary](#)

On Tuesday 01/14/2020 at approximately 13:05 I, Inspector Emily Waldron, conducted a field inspection at Beeman Oil and Gas LLC Elk Springs Unit 3, at 05-081-06472 in Moffat County Colorado.

While there, I observed production.

During this inspection the following possible compliance issues were observed:

Equipment stored on location. See photo 2. Comply with Rule 603.f by 2/14/2020.

Stained soil under pump jack. See photo 3. Comply with Rule 603.f and properly dispose of oily waste in accordance with 907.e by 1/28/2020.

2 drums at wellhead stored without secondary containment. See photo 4. Implement or modify BMPs for improved material handling and spill prevention by 1/20/2020.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 689803597.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

 Comment: 970-326-7533
 970-210-2896

Corrective Action:

Date:

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil under pump jack.		
Corrective Action:	Comply with Rule 603.f . Properly dispose of oily waste in accordance with 907.e.	Date:	01/28/2020
Type	STORAGE OF SUPL		
Comment:	Equipment stored on location.		
Corrective Action:	Comply with Rule 603.f .	Date:	02/14/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	#		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	400 BBLS	Open Top		,	
Comment:						
Corrective Action:		Date:				

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	400 BBLS	HEATED STEEL AST		,	
Comment:						
Corrective Action:		Date:				

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: Waldron, Emily

Earth	Adequate			Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities				
Facility ID: 223110	Type: WELL	API Number: 081-06472	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Pumping.			
Corrective Action:				Date:

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	Drums at wellhead without containment.

Comment: 2 drums at wellhead stored without secondary containment.
No apparent soil migration; erosion or soil movement.

Corrective Action: Implement or modify BMPs for improved material handling and spill prevention.

Date: 01/20/2020

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689803598	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5037752