

Inspection Photos

Location Name: CAERUS PICEANCE LLC Stewart /36-13H (PL36SW),

Location ID: 418660



Photo #0395 photo from SW corner of location.



Photo #0396 NFPA label weathered and not legible.

Inspection Photos

Location Name: CAERUS PICEANCE LLC Stewart /36-13H (PL36SW),

Location ID: 418660




Photo #0398 contents label weathered and not legible



Photo #0397 Unused equipment and debris in 1000 gallon tank containment.

Inspection Photos

Location Name: CAERUS PICEANCE LLC Stewart /36-13H (PL36SW),

Location ID: 418660



Photo #0399 Flowline riser not LO/TO.