

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/08/2020

Submitted Date:

01/08/2020

Document Number:

695101985

**FIELD INSPECTION FORM**

Loc ID 322219 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 74975  
Name of Operator: SAN MARCO PETROLEUM INC  
Address: 240 MILWAUKEE ST STE 200  
City: DENVER State: CO Zip: 80206-

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 7 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Sheridan, John	303-321-0100	sanmarcopetr@cs.com	<a href="#">All Inspections</a>
Marco, San		sanmarcopetr@cs.com	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209942	WELL	PR	01/01/2017	OW	043-06020	ADAMIC 1-20	PR

**General Comment:**

Edited 01/13/2020: Changed CA date for battery signage from 01/09/2020 to 02/10/2020 (24 hr to 30 days). Changed rule citation from 210.d. to 210.b. -Conor Pesicka

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	PHOTO 2: WELL SIGN, CONTACT PHONE NUMBER SIZE IS INADEQUATE AND 911 IS NOT POST ON SIGHT.		
Corrective Action:	INSTALL SIGN THAT COMPLIES WITH RULE 210.b.	Date:	02/10/2020

Emergency Contact Number:

Comment:

Corrective Action:

Date:

**Good Housekeeping:**

Type	OTHER		
Comment:	PHOTO 4: A BULLPLUG ON 210 BBL TANK IS LEAKING. THERE IS AN AREA OF IMPACTED SOIL APP. 3' BY 6' NEAR LEAKING PLUG. CALLED CONTACT NUMBER POSTED ON BATTERY SIGN AND HAD TO LEAVE A MESSAGE.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Properly treat or dispose of oily waste in accordance with 907.e." 24 HOURS TO REPAIR LEAKING BULLPLUG 30 DAYS FOR SOIL. CA DATE 1-9-20.	Date:	01/09/2020

Type	OTHER		
Comment:	PHOTO 3: IT APPEARS THAT WELLHEAD IS LEAKING PRODUCED OIL, AREA OF IMPACTED SOIL APP. 6' BY 3' AROUND WELLHEAD. PHOTO 5: VALVE ON 210 BBL TANK IS SEEPING. THERE IS AN AREA OF IMPACTED SOIL APP3' BY 1' NEAR SEEPING VALVE. PHOTO 6: LOADOUT LINE IS PLUMBED OUTSIDE SECONDARY BMP. THERE IS AN AREA OF IMPACTED SOIL OUSIDE OF BURM) APP. 1' BY 2' AROUND LOADOUT.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Properly treat or dispose of oily waste in accordance with 907.e.	Date:	02/08/2020

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Pump Jack	#		
Comment:	PHOTO 7: APPEARS THAT GEAR BOX ON PUMPJAKE IS LEAKING, THERE IS AN AREA OF IMPACTED SOIL BENEATH GEARBOX.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Properly treat or dispose of oily waste in accordance with 907.f.	Date:	02/08/2020

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 209942 Type: WELL API Number: 043-06020 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: PHOTO 6: LOADOUT LINE IS PLUMBED OUTSIDE SECONDARY BMP. THERE IS AN AREA OF IMPACTED SOIL OUTSIDE OF BURM) APP. 1' BY 2' AROUND LOADOUT.

Corrective Action: INSTALL SECONDARY BMP TO PREENT OILY WASTE FROM MIXING WITH STORM WATER PER RULE 1002.f.

Date: 02/08/2020

Pits:  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402280501	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5031109">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5031109</a>
695101986	INSPECTION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5031105">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5031105</a>