

Construction and Stormwater Inspection

January 10, 2020

Operator: CONFLUENCE DJ LLC- #10518

Location ID: 458676

Inspection Document #: 697501025

Weld County, CO

SWNW Section 4 T4N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Silverton /4 North
Location ID: 458676



Photo 1. Photo taken from the north-central location, facing South. Photo illustrates the western portion of the location has been stabilized with gravel while the eastern portion has been left unconsolidated. Soil particle deposition from wind erosion is apparent. Also, topsoil has been salvaged and stored along the southwestern perimeter of location.

Inspection Photos
Location Name: Silverton /4 North
Location ID: 458676



01.10.2020 13:43

Photo 2. Photo taken from the southeastern location, facing West. Photo illustrates soil particle deposition from wind erosion along the fill slopes, filling up the ditch BMP, and off location.

Inspection Photos
Location Name: Silverton /4 North
Location ID: 458676



Photo 3. Photo taken from the southeastern location, facing East. See comments under Photo 2 regarding soil particle deposition from wind erosion.

Inspection Photos
Location Name: Silverton /4 North
Location ID: 458676



Photo 4. Photo taken from the southeastern location, facing East. See comments under Photo 2 regarding soil particle deposition from wind erosion. Note: Tackifier was observed along the southern fill slope but soil particle deposition has accumulated on top of that.

Inspection Photos
Location Name: Silverton /4 North
Location ID: 458676



Photo 5. Photo taken from the western perimeter of location, facing South. Photo illustrates a ditch and berm BMP installed in conjunction with sediment traps and wattle check dams.

Inspection Photos
Location Name: Silverton /4 North
Location ID: 458676



Photo 6. Photo taken from the northern perimeter of location, facing East. See comments under Photo 5.

Inspection Photos
Location Name: Silverton /4 North
Location ID: 458676



Photo 7. Photo taken from the northern location, facing North. Photo illustrates a stabilized ditch which is directed to the perimeter ditch and berm BMP and sediment trap.

Inspection Photos
Location Name: Silverton /4 North
Location ID: 458676



Photo 8. Photo taken from the northern location, facing Northeast. Photo illustrates one of the sediment traps with a temporarily stabilized outlet.

Inspection Photos
Location Name: Silverton /4 North
Location ID: 458676



Photo 9. Photo taken from the northeastern location, facing North. Photo illustrates another sediment trap with a temporarily stabilized outlet and a stabilized ditch BMP.