

Construction and Stormwater Inspection

January 10, 2020

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Location ID: 462951

Inspection Document #: 697501028

Weld County, CO

NWNW Section 13 T4N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: LATHAM /11-13 CPF
Location ID: 462951



Photo 1. Photo taken from the entrance of the location off HWY 34, facing South.
Photo illustrates a portion of the vehicle tracking device BMP.

Inspection Photos
Location Name: LATHAM /11-13 CPF
Location ID: 462951



Photo 2. Photo taken from the entrance of the location, facing North. Photo illustrates another vehicle tracking device BMP.



Photo 3. Photo taken from the eastern perimeter of the location, facing South. Photo illustrates a ditch BMP. Although there was no observed discharge from location, the ditch BMP has not been constructed in accordance with good engineering practices (i.e., proper depth and 2:1 side slopes).



Photo 4. Photo taken from the northeastern perimeter of location, facing East. Photo illustrates there is no stabilized outlet, only a ditch BMP. Although there was no observed discharge from location, a ditch by itself is not sufficient.

Inspection Photos
Location Name: LATHAM /11-13 CPF
Location ID: 462951



Photo 5. Photo taken from the topsoil stockpile, facing West. Photo illustrates the topsoil stockpile has not been properly stabilized and weed establishment was evident.

Inspection Photos
Location Name: LATHAM /11-13 CPF
Location ID: 462951



Photo 6. Photo taken from the southwestern perimeter of the location, facing South. Photo illustrates an insufficient ditch BMP installed.