

Construction and Stormwater Inspection

January 10, 2020

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Location ID: 434712

Inspection Document #: 697501030

Weld County, CO

SWSE Section 24 T5N R62W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: State Antelope /34-24 Pad
Location ID: 434712



Photo 1. Photo taken from the northern location, facing South. Photo illustrates Operator was in-process of salvaging topsoil. Note: Operator was performing topsoil salvage operations without BMPs along portions of the location.

Inspection Photos
Location Name: State Antelope /34-24 Pad
Location ID: 434712



Photo 2. Photo taken from the northwestern location, facing South. Photo illustrates no BMP has been installed during topsoil salvage operations.

Inspection Photos
Location Name: State Antelope /34-24 Pad
Location ID: 434712



Photo 3. Photo taken from the western perimeter of location, facing East. Photo illustrates the topsoil stockpile area along the southern location. Photo also illustrates the Operator installing a ditch BMP after COGCC staff informed the contractor of the requirement for BMPs during topsoil salvage operations.

Inspection Photos
Location Name: State Antelope /34-24 Pad
Location ID: 434712



Photo 4. Photo taken from the southeastern perimeter of location, facing North. Photo illustrates a ditch BMP which was installed after COGCC staff informed the contractor of the requirement for BMPs during topsoil salvage operations.