

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/08/2020

Submitted Date:

01/16/2020

Document Number:

693700352

FIELD INSPECTION FORM
 Loc ID 327535 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 95620

Name of Operator: WESTERN OPERATING COMPANY

Address: 1165 DELAWARE STREET #200

City: DENVER State: CO Zip: 80204

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Binschus, Chris		chris.binschus@state.co.us	
Hart, Dale	(719) 729-3391	dalehartwoc@fairpoint.net	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
110689	PIT	AC			-	FOSTER 14-1	EI
110690	PIT	AC			-	FOSTER 14-2	EI
247025	WELL	PA	12/10/2014	GW	123-14822	FOSTER 14-2	EI

General Comment:

This is a followup to COGCC Environmental Inspection #693700202 for produced water pit closure. No Form 27 has been received as requested and a Notice of Alleged Violation will be issued for closure of a pit with approved Form 27.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:	Metershed remains on location.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	110689	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI
Facility ID:	110690	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI
Facility ID:	247025	Type:	WELL	API Number:	123-14822	Status:	PA	Insp. Status:	EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID: <u>110690</u>	Lat: <u>40.486753</u>	Long: <u>-104.185128</u>
-------	--------	-----------------------	-----------------------	--------------------------

Reference Point: <input type="text"/>	Other: <input type="text"/>	Length: <input type="text"/>	Width: <input type="text"/>
---------------------------------------	-----------------------------	------------------------------	-----------------------------

Lining:Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Corrective Action: Date:

Produced Water pit present at location documented by Rocket Petroleum Pit Inventory. Pit was on location as late as 2011 and closed prior to 2013 according to aerial images. No Form 27 has been received by COGCC documenting that pit was closed in accordance with Rule 905.b. and compliance with Table 910-1. Former pit coordinates approximately 40.486804 / -104.185168 at a joint battery serving both the Webster 14-1 and 14-2 wells. Location remains in violation of Rule 905.b.

Submit a Form 27 Site Investigation and Remediation Workplan for investigation of the pit closed to demonstrate compliance with Table 910-1.

Type:	Lined:	Pit ID: <u>110689</u>	Lat: <u>40.486753</u>	Long: <u>-104.185118</u>
-------	--------	-----------------------	-----------------------	--------------------------

Reference Point: <input type="text"/>	Other: <input type="text"/>	Length: <input type="text"/>	Width: <input type="text"/>
---------------------------------------	-----------------------------	------------------------------	-----------------------------

Lining:Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**

Netting Type:	Netting Condition:		
Comment:			
Corrective Action			Date:
Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard:	
Comment:	Produced Water pit present at location documented by Rocket Petroleum Pit Inventory. Pit was on location as late as 2011 and closed prior to 2013 according to aerial images. No Form 27 has been received by COGCC documenting that pit was closed in accordance with Rule 905.b. and compliance with Table 910-1. Former pit coordinates approximately 40.486804 / - 104.185168 at a joint battery serving both the Webster 14-1 and 14-2 wells. Location remains in violation of Rule 905.b.		
Corrective Action	Submit a Form 27 Site Investigation and Remediation Workplan for investigation of the pit closed to demonstrate compliance with Table 910-1.		
	Date:		

COGCC Comments

Comment	User	Date
Lack of crop growth is also apparent in the area of the former tank battery and pit. Reclamation issues are referred to COGCC Reclamation Staff.	allisonr	01/10/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693700353	Foster 14-1,2 TankBattery Photos 1-8-2020	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5039557