

Inspection Photos
Operator: BP America
Location/API #: 067-07003
Date: 1-15-2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward. Revegetation is progressing with grasses such as sand drop seed and western wheatgrass. Jointed goatgrass, an annual grass species identified in 2018 inspection needs treatment in spring (before flowering) if present.



Photo 3. View of the western project area from the southwestern corner facing northward. A diversion is installed since the 2018 reclamation inspection. Stormwater erosion needs to be assessed after snow melt/soil thaw.



Photo 4. View of vehicles stored within the eastern project area.



Photo 5. View of reference area, comprised of open pinyon and juniper woodland with sagebrush dominated understory.