

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/06/2020

Submitted Date:

01/10/2020

Document Number:

690101666

FIELD INSPECTION FORMLoc ID 321694 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 51065

Name of Operator: LOEB LLC* HERMAN L

Address: P O BOX 838

City: LAWRENCEVILLE State: IL Zip: 62439

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Welsh, Brian		brian.welsh@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Whittington, Ellice		ellice.whittington@state.co.us	
Hafele, Jeremy		jeremy@loeboil.com	
Pelton, Shane	620-617-5870	shane@loeboil.com	
Middagh, Jesse		jesse@loeboil.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207803	WELL	PR	10/01/2019	OW	017-06738	WHITE AL 2	EG

General Comment:

COGCC Engineering Integrity Inspection; Flowline Inspection Only. The Corrective Actions identified during this field inspection are located in the flowline section of report. Photos uploaded can be accessed via link(s) at end of report.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	# 2		corrective date
Comment:	Electric panel and cathodic rectifier		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Lufkin 320		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 207803 Type: WELL API Number: 017-06738 Status: PR Insp. Status: EG**Flowline**

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: Material:
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: This well is currently producing.

The off location flowline (wellhead line) runs approximately 1300' W-NW from the wellhead to a shared facility/ central tank battery for White AM-1, AL-1, AL-2 wells @ 38.820350/-102.059280. This off location flowline has not been registered with COGCC; Operator has not submitted COGCC Form 44.

Note: Operator has not registered any off location flowlines with COGCC; The Corrective Action outlined is applicable to all wells operated by Herman L. Loeb LLC with off location flowlines.

Corrective Action: Comply with the following COGCC rule (partial description):

1101.a. Off-Location Flowline Registration. (1) An operator must register an off-location flowline constructed on or after May 1, 2018, by submitting a Flowline Report, Form 44, to the Director within 30 days after the flowline is placed into service. An off location flowline in existence prior to May 1, 2018, must be registered by October 31, 2019.

Date: 10/31/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402282388	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034040
690101667	Aerial Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034036
690101668	Signage at pump jack	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034037
690101669	View W-NW from well to battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5034038