



**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	60 BBLS Concrete vault is missing Content and Capacity Labels, see photo 3		
Corrective Action:	Comply with Rule 210.d		Date: 02/10/2020
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:

**Emergency Contact Number:**

Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: _____

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Unmarked Risers North and NW of Separator, see photos 4, 5, & 6		
Corrective Action:	Comply with Rule 603.f		Date: 01/14/2020

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:			Date:

**Equipment:**

Type			corrective date
Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Bradenhead	# 1		
Comment:	Appears to be plumbed to Surface		
Corrective Action:			Date:
Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

Type: Gathering Line	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	60 BBLS	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	500 BBLS	STEEL AST		40.435360,-104.307110

Comment:		
Corrective Action:		Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 431020 Type: WELL API Number: 123-36380 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Thursday 01/09/2020 at approximately 13:53, I, Inspector Erica Petrie, conducted a Field Inspection at Bonanza Creek Energy Operating Company LLC, State Antelope 31-34-3, Location ID #431023 in Weld County, Colorado.                      While there, I observed Production Operations.                      During this inspection the following possible compliance issues were observed:                      Unmarked Risers North and NW od separator. Refer to Rule 603.f about unmarked Risers. See Photos 4, 5, &amp; 6. Comply with Rule 603.f. Corrective Action date 01.14.2020                      60 BBLs Concrete Vault is missing the Content and Capacity labels. See photo 3. Comply with Rule 210.d Corrective Action date 02.10.2020                      A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.                      Continuing Educational Inspections</p>	petrie	01/10/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402282230	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5033814">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5033814</a>
696301111	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5033809">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5033809</a>