

**Inspection Photos**  
**Operator: BP America**  
**Location/API #: 067-09536**  
**Date: 1-15-2020**



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward.



Photo 3. View of cobble within the southeastern project area, although functionality is not assessed due to snow cover. Operator should note that cobble rock is not considered a BMP, as it does not effectively reduce energy of stormwater flows. Course rock is needed where rock is used as a stormwater BMP. Operator needs to continue to monitor stormwater erosion and apply BMPs according to good engineering practices when/where stabilization is needed.



Photo 4. View of reference area, comprised of open pinyon and juniper woodland with sagebrush dominated understory.