

Inspection Photos

API: 05-017-07700

Operator: VECTA OIL & GAS

Inspection Date: 1/14/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-017-07700 | Date: 1/14/2020

Inspection Photos




Photo 1. Facing south along the former access road. This area is bare of vegetation. Soils did not seem to be compacted but should be evaluated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07700 | Date: 1/14/2020

Inspection Photos



Photo 2. Center of the location facing south.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07700 | Date: 1/14/2020

Inspection Photos



Photo 3. Center of the location facing west.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07700 | Date: 1/14/2020

Inspection Photos



Photo 4. Center of the location facing east.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07700 | Date: 1/14/2020

Inspection Photos



Photo 5. Facing north toward the eastern side of the location. This area is bare of vegetation. Approximately 200 ft. x 75 ft. area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07700 | Date: 1/14/2020

Inspection Photos



Photo 6. Facing east toward the undisturbed pasture.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07700 | Date: 1/14/2020