

Inspection Photos

API: 05-017-07717

Operator: VECTA OIL & GAS

Inspection Date: 1/14/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-017-07717 | Date: 1/14/2020

Inspection Photos



Photo 1. Facing south toward the location. There is a cattle guard that remains at the location which needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07717 | Date: 1/14/2020

Inspection Photos



Photo 2. Center of the location facing north. Native vegetation appears to be fully established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07717 | Date: 1/14/2020

Inspection Photos



Photo 3. Center of the location facing west. Native vegetation appears to be fully established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07717 | Date: 1/14/2020

Inspection Photos



Photo 4. Center of the location facing east. Native vegetation appears to be fully established.



Inspection Photos



Photo 5. Center of the location facing south. Native vegetation appears to be fully established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07717 | Date: 1/14/2020

Inspection Photos



Photo 6. Facing east toward the undisturbed pasture.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 05-017-07717 | Date: 1/14/2020