

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/15/2020

Submitted Date:

01/17/2020

Document Number:

693801325**FIELD INSPECTION FORM**Loc ID 322412 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Contact, General		regulatory@foundationenergy.com	All inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210441	WELL	SI	08/01/2019	GW	045-06197	FEDERAL 31-16	SI

General Comment:

COGCC staff performed a routine field inspection on 1/15/2020. See inspection text and photos for details.
Issues were found requiring corrective action. CA(s) from previous inspection not completed.
Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location				
Lease Road:				
Type	Main			
comment:				
Corrective Action	L			Date:
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Sign at meter housing			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	303-220-7772, 970-858-7490,911			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Weeds and debris removed. CA completed from previous inspection.			
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:	Spill noted on previous inspection appears to be remediated. CA completed.			
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Hogwire & T-post			
Corrective Action:				Date:
Type	PIT			
Comment:	No netting or fencing (where fencing or netting required by pit permit). Netting or fencing not maintained. CA not completed from previous inspection Doc#689401733			
Corrective Action:	Pit is being closed under approved F-27 (Doc# 401962561) with a date of commencement of Remediation of 6/3/2019. Inspector believes that the fence was removed for remediation activities. CA date set for completion of remediation, 10/7/2019 (Doc# 401962561).			Date: 10/07/2019
Type	OTHER			
Comment:	Hogwire & T-post fence at meter housing			

Corrective Action:		Date:	
Equipment:		corrective date	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Dehydrator	# 0		
Comment: Equipment removed			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		39.373415,-108.991402
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	210441	Type:	WELL	API Number:	045-06197	Status:	SI	Insp. Status:	SI
Producing Well									
Comment:	Flowing								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: NOPit ID: 400998069Lat: 39.373369Long: -108.991400Reference Point: SEOther: Length: 20Width: 20**Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: See fencing section for detailsCorrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: Comment: Corrective Action: Date:

Permit:	Facility ID	Permit Num	Expiration Date
	119480	400998069	<input type="text"/>

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
693801334	Inspection photos 1/15/2020	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5041217