

# Inspection Photos

API: 05-017-07715

Operator: VECTA OIL & GAS

Inspection Date: 1/14/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-017-07715 | Date: 1/14/2020

## Inspection Photos



**Photo 1.** Facing south along the former access road.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

API: 05-017-07715 | Date: 1/14/2020



## Inspection Photos



**Photo 2.** Center of the location facing south. Native vegetation is well established in the southern portion of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-07715 | Date: 1/14/2020



## Inspection Photos



**Photo 3.** Center of the location facing west. There is undesirable weeds towards the western portion of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-07715 | Date: 1/14/2020



## Inspection Photos



**Photo 4.** Facing west at the center of the location. The area highlighted is predominately undesirable weeds (Kochia).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-07715 | Date: 1/14/2020



## Inspection Photos



**Photo 5.** Center of the location facing east. Native vegetation is established well at the east portion of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-07715 | Date: 1/14/2020