

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/13/2020

Submitted Date:

01/13/2020

Document Number:

679602165

**FIELD INSPECTION FORM**

Loc ID 453075 Inspector Name: Santistevan, Brittani On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10459  
Name of Operator: EXTRACTION OIL & GAS INC  
Address: 370 17TH STREET SUITE 5300  
City: DENVER State: CO Zip: 80202

**Findings:**

- 20 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@extractionog.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453069	WELL	PR	08/15/2018	OW	123-45900	Hergert South 35W-15-1C	PR
453070	WELL	PR	08/23/2018	OW	123-45901	Hergert South 35W-15-5N	PR
453071	WELL	PR	05/01/2019	OW	123-45902	Hergert South 35W-15-8N	PR
453072	WELL	PR	09/06/2018	OW	123-45903	Hergert South 35W-15-4N	PR
453073	WELL	PR	09/06/2018	OW	123-45904	Hergert South 35W-15-11N	PR
453074	WELL	PR	09/06/2018	OW	123-45905	Hergert South 35W-15-2N	PR
453076	WELL	PR	09/02/2018	OW	123-45906	Hergert South 35W-15-10N	PR
453077	WELL	PR	07/01/2018	OW	123-45907	Hergert South 35W-15-7C	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment at various places on location. See attached photos.		
Corrective Action:	Comply with Rule 603.f.	Date:	01/20/2020
Type	TRASH		
Comment:	Bucket near condensate tank. See attached photo.		
Corrective Action:	Comply with Rule 603.f.	Date:	01/20/2020

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

**Equipment:**

Type: Emission Control Device	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 20		
Comment:	+4 = 24.		
Corrective Action:		Date:	

Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 20		
Comment:	+8 = 28.		
Corrective Action:			Date:
Type: Compressor	# 9		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 8		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	OTHER	BV CONCRETE		,
Comment:					
Corrective Action:					
					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	60 BBLS	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	OTHER	BV CONCRETE		,
Comment:					
Corrective Action:					
					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	60 BBLS	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares containment with other tanks.				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares containment with other tanks.				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	<50 BBLS	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	8	400 BBLS	STEEL AST		40.534100,-104.854100

Comment:		
Corrective Action:		Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	453069	Type:	WELL	API Number:	123-45900	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	453070	Type:	WELL	API Number:	123-45901	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	453071	Type:	WELL	API Number:	123-45902	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	453072	Type:	WELL	API Number:	123-45903	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	453073	Type:	WELL	API Number:	123-45904	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	453074	Type:	WELL	API Number:	123-45905	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	453076	Type:	WELL	API Number:	123-45906	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	453077	Type:	WELL	API Number:	123-45907	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				

--

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>  <b>**Weather Conditions: SUNny, muddy/snow on ground</b>                      On Monday, January 13, 2020 at approximately 14:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at HERGERT 35-L PAD (Extraction Oil &amp; Gas), at location #: 453075 in WELD COUNTY Colorado.                      While there, I observed a producing location.                      During this inspection the following possible compliance issues were observed:                      1. Unused equipment on various spots of location. PLEASE REMOVE TO COMPLY WITH RULE 603.F. (Corrective Action Date: January 20, 2020) See attached photo #13, 16, 17, 18.                      2. Trash near tank (condensate tank on east side of location) PLEASE REMOVE TO COMPLY WITH RULE 603.F. (Corrective Action Date: January 20, 2020) See attached photo #19.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	santistb	01/13/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402284371	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5036311">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5036311</a>
679602166	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5036306">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5036306</a>