

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/09/2020

Submitted Date:

01/13/2020

Document Number:

692401783**FIELD INSPECTION FORM**Loc ID 334618 Inspector Name: Colby, Lou On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Burger, Craig		craig.burger@state.co.us	
		cogcc.inspections@caerusoila ndgas.com	
Ramsey, Scott		scott.ramsey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280630	WELL	PR	07/29/2008	GW	045-11302	MCU 26-8C (D25W)	RI
280631	WELL	PR	09/20/2006	GW	045-11301	HMU 26-1C (D25W)	RI
291925	WELL	PR	07/26/2008	GW	045-14546	HMU 25-3D(D25W)	RI

General Comment:

This is an Interim Reclamation & Stormwater focused Inspection. Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

Inspected Facilities									
Facility ID:	280630	Type:	WELL	API Number:	045-11302	Status:	PR	Insp. Status:	RI
Producing Well									
Comment:	Valve (appears from lower casing) is open, venting loudly. Tag has note to Leave Open Venting. Form 4: Doc#2055433 Dated 2/13/12, has OTHER Box checked -- CONTINUOUS BRADENHEAD VENT and Request to Vent or Flare Box checked. No other, more current/relevant Docs could be found in Files.								
Corrective Action:	Check with COGCC Area Engineer about Status of this Well.					Date:	01/22/2020		
Facility ID:	280631	Type:	WELL	API Number:	045-11301	Status:	PR	Insp. Status:	RI
Facility ID:	291925	Type:	WELL	API Number:	045-14546	Status:	PR	Insp. Status:	RI

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____ Pass _____

Comment Four strand wire

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____ Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____ Pass _____

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? FailComment Cellars of two Wells allow ingress to cellars by small wildlife with no means of egress.Corrective Action Cover cellars, or as these are shallow cellars install means of Wildlife egress, or fill in cellar if practical. Date **02/13/2020**

Guy line anchors marked? _____

Comment _____

Corrective Action _____ Date _____

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Site appears stable, though snow cover prevented detailed assessment.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402283739	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5035767
692401784	Inspection Photos RI	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5035766