

Inspection Photos

Location Name: Pointer 43-25 followup ca date 2-17-20

API#: 05-071-09766

INSP. #: 695102060



Colorado Oil & Gas Conservation Commission
37.22943, -104.83246, 2267.0m, 65°
2020/01/17 10:12:49

PHOTO 1: LOCATION



Colorado Oil & Gas Conservation Commission
37.22943, -104.83229, 2237.0m, 295°
2020/01/17 10:14:49

PHOTO 2: WELL SIGN



Inspection Photos

Location Name: Pointer 43-25 followup ca date 2-17-20

API#: 05-071-09766

INSP. #: 695102060



PHOTO 3: PIT LINER IS DETERIORATING THERE ARE SEVERAL PLACES WHERE LINER IS CRACKED AND TORN THIS IS THE SECOND NOTICE OF PIT LINER NOT MAINTAINED, IF CA IS NOT ADDRESSED BY THE NEXT INSPECTION ENFORCEMENT MAY BE CONSIDERED. MAINTAIN LINER IN ACCORDANCE WITH RULE 904. CA DATE 2-17-20

PHOTO 4: ANOTHER IMAGE OF PIT LINER DETERORATION.

Inspection Photos

Location Name: Pointer 43-25 followup ca date 2-17-20

API#: 05-071-09766

INSP. #: 695102060



PHOTO 5: ANOTHER IMAGE OF PIT LINER DETERORATION.



PHOTO 6: PEACES OF PIT LINER APP. 60' TO THE NORTHWEST OF PIT (THERE ARE PIECES OF LINER IN SEVERAL PLACES ON LOCATION AND AROUND LOCATION OFF PAD). **POLICE LOCATION AND SURROUNDING AREA FOR PIECES OF PIT LINER AND DISPOSE IN ACCORDANCE WITH GOOD HOUSEKEEPING RULE 603.f. CA DATE 2-17-20**