

Inspection Photos
Location Name: CORTINA 23-25
API#: 05-071-08340
INSP. #: 695102063



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

Inspection Photos

Location Name: CORTINA 23-25 CA DATE 2-1-20

API#: 05-071-08340

INSP. #: 695102063



PHOTO 3: IT APPEARS THAT THE DRIVEHEAD HYDRAULIC MOTOR IS LEAKING FLUID. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. CA DATE 2-1-20

PHOTO 4: AREA OF IMPACTED SOIL UNDER DRIVEHEAD MOTOR APPEARS TO BE FROM LEAKING HYDRAULIC MOTOR. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 1-22-20.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CORTINA 23-25 CA DATE 2-1-20

API#: 05-071-08340

INSP. #: 695102063



PHOTO 5: PRODUCED WATER IN EARTH PIT IS ABOVE 2' FREEBOARD (SPOKE WITH ED ROMERO BY PHONE TO HAVE FLUID LEVEL REDUCED). REDUCE FLUID IN PIT TO MAINTAIN AT LEAST 2' OF FREEBOARD IN PIT PER RULE 902.b. CA DATE 1-18-20