

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/14/2020

Submitted Date:

01/14/2020

Document Number:

679602168**FIELD INSPECTION FORM**Loc ID 435175 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10311Name of Operator: SRC ENERGY INCAddress: 1675 BROADWAY SUITE 2600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**16 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@srcenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435172	WELL	PR	05/19/2015	OW	123-38493	Weld 152 41-10CHZ	PR
435173	WELL	PR	04/03/2015	OW	123-38494	Weld 152 41-10NHZ	PR
435174	WELL	PR	10/31/2017	OW	123-38495	Weld 152 31-10CHZ	PR
435175	LOCATION	AC			-	Weld 152 31-10CHZ	AC
435189	WELL	PR	04/03/2015	OW	123-38501	Weld 152 C-10CHZ	PR
435190	WELL	PR	04/06/2015	OW	123-38502	Weld 152 C-10NHZ	PR
435191	WELL	PR	04/07/2015	OW	123-38503	Weld 152 31-10NHZ	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	3 tanks missing labeling. See attached photos.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	07/18/2019

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained soil in each separator house. See attached photos.		
Corrective Action:	Comply with Rules 1002.f.(2).d. and 605.d.	Date:	02/14/2020
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment near ECDs, near separators, unused risers. See attached photos.		
Corrective Action:	Comply with Rule 603.f.	Date:	02/14/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:			
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Vertical Heater Treater	# 2		
Comment:	1 disconnected		
Corrective Action:		Date:	
Type: Bird Protectors	# 12		
Comment:			
Corrective Action:		Date:	

Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 6		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 6		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	2	OTHER	FIBERGLASS AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)	UNKNOWN	
Other (Capacity)	UNKNOWN	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with other tanks.				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	12	400 BBLs	STEEL AST		40.502000,-104.883200
Comment:					
Corrective Action:					

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	435172	Type:	WELL	API Number:	123-38493	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	435173	Type:	WELL	API Number:	123-38494	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	435174	Type:	WELL	API Number:	123-38495	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	435175	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	AC
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	435189	Type:	WELL	API Number:	123-38501	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	435190	Type:	WELL	API Number:	123-38502	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	435191	Type:	WELL	API Number:	123-38503	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 679601028. All, but one corrective action assigned in previous inspection DOC#: 679601028 has been resolved. Previous corrective action has been re-assigned to this location with original corrective date. TWO (2) NEW corrective actions have been assigned to this location. Review my inspection, photos, and previous inspection DOC#: 679601028 for additional information on this location.</p> <p>COGCC Inspection Report Summary  **Weather Conditions: sunny, snow on ground</p> <p>On Tuesday, January 14, 2020 at approximately 10:20, I, Inspector Brittani Santistevan, conducted an on-site inspection at WELD 152 31-10CHZ (SRC Energy), at location #: 435175 in WELD COUNTY Colorado.</p> <p>While there, I observed a producing facility.</p> <p>During this inspection the following possible compliance issues were observed:</p> <ol style="list-style-type: none"> <li>1. No labeling on 3 tanks (one steel, 2 fiber glass). INSTALL SIGN TO COMPLY WITH RULE 210.D. (Corrective Action Date: July 18, 2019) See attached photos #3-5.</li> <li>2. Unused equipment on various areas of location. (empty methanol barrels, unused risers near southwest end of separators, disconnected heater treater and unused risers) REMOVE/LOTO TO COMPLY WITH RULE 603.F. (Corrective Action Date: February 14, 2020) See attached photos #6-8.</li> <li>3. Appears stained soil was previously removed, but accumulated again in each separator house. PLEASE REMOVE AND COMPLY WITH RULES 1002.F.(2).D AND 605.D. (Corrective Action Date: February 14, 2020) See attached photos #9-14.</li> </ol> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.  This is a summary of inspection report.</p>	santistb	01/14/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402285799	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5037569">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5037569</a>
679602169	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5037552">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5037552</a>