

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/14/2020

Submitted Date:

01/14/2020

Document Number:

697600752**FIELD INSPECTION FORM**Loc ID 317790 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		MKnop@kpk.com	
Allison, Rick		rick.allison@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Kauffman, KP		cogcc@kpk.com	All Inspections

**General Comment:**

inspection of spill/release related to flowline in corn field approximately 1,050 feet south west of battery facility. Battery itself was not inspected in this report

**Environmental****Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: \_\_\_\_\_

Comment: complainant reported that oil daylighted from ground as he observed when working crop field this fall.

Corrective Action: investigate spill and determine approximate quantity and general cause of spill/release within 72 hours and report those findings to COGCC. Complainant reported first noticing spill area a a problem when working the field in spring of 2019. Provide rough sketch of flowlines in area related to Nesssu wells and Nessu tank battery as shown on attached 2019 aerial image.

Date: 01/17/2020

Reportable: YES

GPS: Lat 40.129619

Long -104.798581

Proximity to Surface Water:

Depth to Ground Water:

**Water Well Complaint:**

Lat

Long

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402285957	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5037758">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5037758</a>
697600753	annotated aerial image	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5037754">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5037754</a>
697600754	photo of spill area as reported by complainant	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5037755">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5037755</a>