

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/14/2020

Submitted Date:

01/14/2020

Document Number:

699100903

FIELD INSPECTION FORMLoc ID 425450 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|--|-----------------|
| , | | NBL_DJBU_Inspections@NB LENERGY.COM | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 425451 | WELL | PA | 02/17/2016 | GW | 123-34390 | OSTER C19-27D | PA |
| 425452 | WELL | PR | 10/01/2019 | GW | 123-34391 | NEI C17-33D | PR |
| 425453 | WELL | PR | 10/01/2019 | GW | 123-34392 | NEI C18-24D | PR |
| 425454 | WELL | PR | 03/01/2019 | OW | 123-34393 | NEI C18-23D | PR |
| 425455 | WELL | PR | 10/01/2019 | GW | 123-34394 | NEI C18-32D | PR |
| 425456 | WELL | PR | 10/01/2019 | GW | 123-34395 | NEI C18-33D | PR |
| 425457 | WELL | PR | 10/01/2019 | GW | 123-34396 | NEI C18-21D | PR |
| 425462 | WELL | PR | 10/01/2019 | GW | 123-34398 | NEI PC C18-20D | PR |
| 425463 | WELL | PR | 10/01/2019 | GW | 123-34399 | NEI C18-22D | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | TRASH | | |
| Comment: | Trash next to the meter run needs to be removed for good housekeeping. See attached photo. | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 01/23/2020 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|----------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Panel X8 | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Pig Station | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-------------------------------|-----|--|-------|
| Type: Bird Protectors | # 5 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 5 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 8 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 8 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Emission Control Device | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| | | | | | | |
|--------------------|--|----------|-------------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 3 | OTHER | BV CONCRETE | | , | |
| Comment: | Shares Containment with crude oil tanks. | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 60 BBL | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

| | | | | | | |
|--------------------|---|----------|-----------|---------|-----------------------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CRUDE OIL | 3 | 300 BBLs | STEEL AST | | 40.311750,-104.596040 | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

Inspector Name: Burns, Adam

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Concrete | Adequate | Walls Sufficent | Base Sufficent | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 425451 Type: WELL API Number: 123-34390 Status: PA Insp. Status: PA

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Plugged and Abandoned

Corrective Action: _____ Date: _____

Facility ID: 425452 Type: WELL API Number: 123-34391 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 425453 Type: WELL API Number: 123-34392 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 425454 Type: WELL API Number: 123-34393 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 425455 Type: WELL API Number: 123-34394 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 425456 Type: WELL API Number: 123-34395 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 425457 Type: WELL API Number: 123-34396 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 425462 Type: WELL API Number: 123-34398 Status: PR Insp. Status: PR

Producing WellComment: [PR](#)

Corrective Action:

Date:

Facility ID: 425463 Type: WELL API Number: 123-34399 Status: PR Insp. Status: PR**Producing Well**Comment: [PR](#)

Corrective Action:

Date:

COGCC Comments

| Comment | User | Date |
|---|--------|------------|
| <p>COGCC Inspection Report Summary On Tuesday 1/14/20 at approximately 0847 hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Oster C 19-27D Facility of Noble Energy, at Location ID: 425450 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Trash next to meter run needs to be removed for good housekeeping. See attached photos. Comply with Rule 603.f . With a corrective action date of 1/23/20 See attached photos A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. Continuing education inspections</p> | burnsa | 01/14/2020 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402285107 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5036972 |
| 699100904 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5036969 |