

Inspection Photos

API: 05-121-11025

Operator: DAVIS, LLC* EDWARD MIKE

Inspection Date: 1/15/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-121-11025 | Date: 1/15/2020

Inspection Photos



Photo 3. Center of the location facing north.



COLORADO
**Oil & Gas Conservation
Commission**
Department of Natural Resources

API: 05-121-11025 | Date: 1/15/2020

Inspection Photos



Photo 2. Center of the location facing west.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 05-121-11025 | Date: 1/15/2020

Inspection Photos



Photo 4. Center of the location facing east.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 05-121-11025 | Date: 1/15/2020

Inspection Photos



Photo 5. Center of the location facing south.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 05-121-11025 | Date: 1/15/2020

Inspection Photos



Photo 6. View of groundcover shows predominately undesirable weeds at the location.



Inspection Photos




Photo 7. Facing west at the beginning of transect at the disturbed location.



Photo 8. Ground cover at midpoint along the transect at the disturbed location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos



Photo 9. Facing south along the transect at the disturbed location.



Photo 10. Facing north along the transect at the disturbed location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos



Photo 11. Facing east at the end of the transect at the disturbed location.



Photo 12. Facing northeast at the beginning of the transect at the undisturbed reference site.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos



Photo 13. Ground cover at midpoint along the transect at the undisturbed reference site.



Photo 14. Facing northwest along the transect at the undisturbed reference site.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos



Photo 15. Facing southeast along the transect at the undisturbed reference site.



Photo 16. Facing southwest at the end of the transect at the undisturbed reference site.



Cover Data

Date: 1/15/2020 Inspected By: Ryan Stephen

Location/Operator: API# 121-11025 Davis LLC

[illegible]

2nd= second hit; P= plant species present but not hit