

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/15/2020

Submitted Date:

01/15/2020

Document Number:

699300922**FIELD INSPECTION FORM**

Loc ID 333015 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259827	WELL	PR	08/08/2007	GW	123-20385	SHELEY 24-4	PR
276738	WELL	PR	12/01/2017	OW	123-22822	SHELEY 4-6-4	PR

**General Comment:**

### Location

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Methanol Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Dead weeds all around wellsite & wellheads		
Corrective Action:	Comply with rule 603.f	Date:	01/22/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	IGNITOR/COMBUSTOR		
Comment:	Chainlink topped with barb wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Chain link topped with barbwire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	AG fence		
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date
Type: Vertical Heated Separator	# 4			
Comment:				
Corrective Action:				Date:
Type: Compressor	# 1			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 10			
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 2			
Comment:	Appear to e plumbed to surface			
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 2			
Comment:	Automation			
Corrective Action:				Date:
Type: Plunger Lift	# 2			
Comment:				
Corrective Action:				Date:
Type: Emission Control Device	# 6			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 4			
Comment:				
Corrective Action:				Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	235 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Inspector Name: Revas, Robbie

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares containment with condensate tanks					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	10	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:
<b>Paint</b>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**Facility ID: 259827 Type: WELL API Number: 123-20385 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 276738 Type: WELL API Number: 123-22822 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 1/15/2020 at approximately 1330 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Crestone Peak Resources location:</p> <p style="text-align: right;">Sheley 24-4 &amp; 4-6-4 at</p> <p>Location #333015 in Weld County Colorado.</p> <p>While there, I observed a producing wellsite.</p> <p>During this inspection the following compliance issue was observed:</p> <p>603.f Housekeeping: Dead weeds all around wellsite. CA date 1/22/2020.</p> <p>See attached photos 1-6.</p> <p>Location is dry, weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	01/15/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402287220	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5039051">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5039051</a>
699300923	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5039042">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5039042</a>
699300925	TB pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5039043">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5039043</a>