

Construction and Stormwater Inspection

January 10, 2020

Operator: SRC ENERGY INC- #10311

Location ID: 419489

Inspection Document #: 697501052

Weld County, CO

NENW Section 18 T6N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Lincoln State /3-18 Pad

Location ID: 419489




Photo 1. Google Earth aerial imagery taken 7/17/2019. Photo illustrates this location is out of compliance with Rule 1003 for interim reclamation at the well location. Interim reclamation should have been completed by 7/7/2019.

Note: At the time of this inspection on 1/10/2020, interim reclamation had not yet been completed.

Inspection Photos
Location Name: Lincoln State /3-18 Pad
Location ID: 419489



Photo 2. Photo taken from the western topsoil stockpile, facing South. Photo illustrates a topsoil stockpile. Appears the Operator has attempted to seed into the topsoil stockpile. Operator should establish perennial vegetation to ensure compliance with Rule 1002.c.

Note: Operator built this location June 2018. This location is technically out of compliance with Interim Reclamation rules- see Photo 1.

Inspection Photos
Location Name: Lincoln State /3-18 Pad
Location ID: 419489



Photo 3. Photo taken from the western perimeter of location, facing North. Photo illustrates the ditch BMP which is directed to a stabilized outlet (sediment trap).

Inspection Photos
Location Name: Lincoln State /3-18 Pad
Location ID: 419489



Photo 4. Photo taken from the southeastern perimeter of location, facing North. Photo illustrates the ditch BMP which is directed to a stabilized outlet (sediment trap).

Inspection Photos
Location Name: Lincoln State /3-18 Pad
Location ID: 419489



Photo 5. Photo taken from the eastern perimeter of location, facing North. Photo illustrates the ditch BMP which is directed to a stabilized outlet (sediment trap).

Inspection Photos
Location Name: Lincoln State /3-18 Pad
Location ID: 419489



Photo 6. Photo taken from the northeastern perimeter of location, facing Northwest. Photo illustrates the stabilized outlet (sediment trap). Appears to be in proper functioning condition at the time of this inspection.