

Inspection Photos
Location Name: Rocky MTn Fuel CO C #1 & NRC 9-9-15H
Location ID: 317650



Photo 1 WH sign CO C #1



Photo 2 Stained soil around well head CO C #1

Inspection Photos
Location Name: Rocky MTn Fuel CO C #1 & NRC 9-9-15H
Location ID: 317650



Photo 3 Weeds around Guy line anchor on location



Photo 4 Weeds around Guy line anchor on location

Inspection Photos
Location Name: Rocky MTn Fuel CO C #1 & NRC 9-9-15H
Location ID: 317650



Photo 5 Weeds around Guy line anchor on location



Photo 6 NRC 9-9-15H WH sign. Weeds around well head

Inspection Photos
Location Name: Rocky MTn Fuel CO C #1 & NRC 9-9-15H
Location ID: 317650



Photo 7 Unmarked unused riser not LOTO



**Photo 8 unused equipment Pumping unit cement base.
Weeds around Well head**

Inspection Photos

Location Name: Rocky MTn Fuel CO C #1 & NRC 9-9-15H

Location ID: 317650



Photo 9 Electric panel



Photo 10 TNK BTRY



Inspection Photos

Location Name: Rocky MTn Fuel CO C #1 & NRC 9-9-15H

Location ID: 317650



Photo 11 Sep/meter house and ECD




Photo 12 unmarked unused and not loto risers inside crude oil containment.

Inspection Photos
Location Name: Rocky MTn Fuel CO C #1 & NRC 9-9-15H
Location ID: 317650



Photo 13 Mechanical issue and stained soil around crude oil tank 2" line



Photo 14 Mechanical issue and stained soil around crude oil tank 2" line

Inspection Photos

Location Name: Rocky MTn Fuel CO C #1 & NRC 9-9-15H

Location ID: 317650



Photo 15 NFPA placards faded need to be replaced.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources