

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/22/2020

Submitted Date:

01/22/2020

Document Number:

688306814**FIELD INSPECTION FORM**Loc ID 320704 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 76175Name of Operator: SANDLIN OIL CORPAddress: 1580 LINCOLN ST SUITE 580City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Crowner, Linda	303-292-3313	ljcsandlin@aol.com	Designated Agent
Sandlin, Kathie	(303) 292-3313	sandlinoilcorporation@gmail.com	Principal Agent
Chesson, Robert		robert.chesson@state.co.us	COGCC EPS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204561	WELL	PR	05/01/2018	OW	005-06646	TIPPET-CARLSON 1	PR

General Comment:

Reinspection. Corrective action was completed (Form 19I and S were submitted. Stained soil is on plastic and bermed. Bradenhead is plumbed to surface.)

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	#		corrective date
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 204561	Type: WELL	API Number: 005-06646	Status: PR	Insp. Status: PR
Producing Well				
Comment:	PR.			
Corrective Action:				Date:

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles	Adequate		
Comment	stained soil from flowline spill at treater is on plastic and bermed			
Corrective Action				Date:

Spill/Remediation:

Comment:				
Corrective Action:				Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688306824	Sandline Tippet-Carlson 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5045431