

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 3: THERE IS APP. 1" TO 2" OF STANDING OIL INSIDE ENGINE SKID (ALTHOUGH ENGINE SKID IS INSIDE A BUILDING THE GARAGE STYLE DOOR IS FULL OPEN AT TIME OF INSPECTION ALLOWING WILDLIFE TO BE ABLE TO GET TO IT).		
Corrective Action:	Comply with general provisions of the oil and gas act for wildlife protection.		Date: 01/20/2020

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Flaring:

Type		
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Inspected FacilitiesFacility ID: 295001 Type: WELL API Number: 071-09529 Status: PR Insp. Status: PR**Workover**Comment: Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402287294	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5039180
695102017	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5039177