

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/21/2020

Submitted Date:

01/23/2020

Document Number:

693801352**FIELD INSPECTION FORM**Loc ID 312505 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 50910Name of Operator: LINN BROS OIL & GAS INC.Address: P O BOX 416City: FRUITA State: CO Zip: 81521-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------|-----------------|
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| Linn, Cathy | 970-858-3733 | clinn@fruitawireless.com | All Inspection |
| Browning, Chuck | 970-433-4139 | chuck.browning@state.co.us | Field Inspector |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------------------|-------------|
| 221803 | WELL | PR | 01/09/2016 | GW | 077-08405 | FEDERAL/SINCLAIR/IMMI CH 1-24 | PR |

General Comment:

COGCC staff performed a routine field inspection on 1/21/2020.
No issues were found. See inspection text and photos for details.

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | Date: | |
| Type | Main | | |
| comment: | | | |
| Corrective Action | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 970-261-2884 or 911

Corrective Action:

Date: _____

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|----------------|-------|--|
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Hogwire | | |
| Corrective Action: | | Date: | |
| Type | PIT | | |
| Comment: | Hogwire & pipe | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|----------------------------|-----|--|-------|
| Type: Horizontal Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|-----------|---------|-----------------------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | 300 BBLs | STEEL AST | | 39.356188,-109.047928 | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | |
|----------------------|------------|-----------------------|------------|
| Facility ID: 221803 | Type: WELL | API Number: 077-08405 | Status: PR |
| Insp. Status: PR | | | |
| Producing Well | | | |
| Comment: | Pumping | | |
| Corrective Action: | | Date: | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: NO

Pit ID:

Lat: 39.356246Long: -109.048037Reference Point: SE

Other: _____

Length: 15Width: 15**Lining:**

Liner Type:

Liner Condition:

Comment:

Corrective

Date:

Fencing:Fencing Type: WildlifeFencing Condition: Adequate

Comment:

Corrective

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective

Date:

Anchor Trench Present:

Oil Accumulation: NO2+ feet Freeboard: YES

Comment:

Corrective

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------------|---|
| 693801371 | Inspection photos 1/21/2020 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5046585 |