

Inspection Photos

API: 05-043-06207

Operator: JAVERNICK OIL

Inspection Date: 1/23/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06207 | Date: 1/23/2020

Inspection Photos



Photo 1. Facing south toward the location. Well sign is posted at the fence H brace.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06207 | Date: 1/23/2020

Inspection Photos



Photo 2. Facing southwest toward the location. Interim reclamation has not been performed at this location. Unused areas of the location must be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06207 | Date: 1/23/2020

Inspection Photos



Photo 3. Aerial image shows the location and the outline shows approximately the size of the location it should be reduced to. Unused areas of the location must be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06207 | Date: 1/23/2020

Inspection Photos



Photo 4. The drilling pit has not been closed and reclaimed as required.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06207 | Date: 1/23/2020

Inspection Photos



Photo 5. The topsoil pile at the west side of the location is bare and not stabilized. Part of the topsoil needs to be used for interim reclamation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06207 | Date: 1/23/2020

Inspection Photos



Photo 6. The pumpjack appears to be disconnected. Well status appears to be shut in.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06207 | Date: 1/23/2020

Inspection Photos



Photo 7. The tank does not have the required labeling.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06207 | Date: 1/23/2020