

Inspection Photos

Operator: Catamount Energy
Location/API #: 067-10019
Date: 1-22-2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the western cut-slope from the western edge facing northward.



Photo 3. View of erosional channels that remain in the western project area.




Photo 4. View of erosional channel that remains on the southwestern project area.



Photo 5. View of metal debris within the southwestern project area.



Photo 6. View of Russian knapweed in the western project area.