

Inspection Photos

API: 05-043-06219

Operator: AUSCO PETROLEUM INC

Inspection Date: 1/23/2020



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06219 | Date: 1/23/2020

Inspection Photos



Photo 1. Facing northwest along the access road. Stormwater controls appear to be maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06219 | Date: 1/23/2020

Inspection Photos



Photo 2. Facing north toward the location. Well sign is posted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06219 | Date: 1/23/2020

Inspection Photos



Photo 3. Facing northeast at the location. There is 11 frac tanks staged at this location. The tanks need to be removed so interim reclamation can be performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06219 | Date: 1/23/2020

Inspection Photos



Photo 4. Facing north toward the location. Interim reclamation has not been performed. Unused areas must be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06219 | Date: 1/23/2020

Inspection Photos



Photo 5. West side of the location facing northeast. Unused areas of the location must be reclaimed. Disturbed soils are susceptible to erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06219 | Date: 1/23/2020

Inspection Photos



Photo 6. There is a pipe riser at west side that is not clearly visible or protected.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06219 | Date: 1/23/2020

Inspection Photos



Photo 7. Wattle are displaced in areas around the location. BMP's must be maintained at all times.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06219 | Date: 1/23/2020

Inspection Photos



Photo 8. Topsoil pile at west side of the location. The topsoil pile is not stabilized and protected. A portion of the topsoil will need to be used for interim reclamation. The remaining portion must be seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06219 | Date: 1/23/2020

Inspection Photos



Photo 9. North side of the location facing east. The wattles are displaced and disturbed soils are not stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06219 | Date: 1/23/2020

Inspection Photos



Photo 10. The berms around the tank battery are not compacted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06219 | Date: 1/23/2020

Inspection Photos



Photo 11. The secondary containment around the tank is not adequate to contain spill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06219 | Date: 1/23/2020

Inspection Photos



Photo 12. East side of the location facing west.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06219 | Date: 1/23/2020

Inspection Photos



Photo 13. Facing toward northeast area of the location. The disturbed soils are susceptible to erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06219 | Date: 1/23/2020

Inspection Photos



Photo 14. There is a hole at the east side of location which may be an incomplete sediment trap. BMP's must be implemented in accordance with good engineering practice and must be maintained at all times.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06219 | Date: 1/23/2020

Inspection Photos



Photo 15. There are wattles installed around the southeast perimeter however stormwater will run down hill along the wattles.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06219 | Date: 1/23/2020

Inspection Photos



Photo 16. Facing northeast at the location. The tanks need to be removed so interim reclamation can be performed. This area needs to be recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06219 | Date: 1/23/2020