

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/16/2020

Submitted Date:

01/27/2020

Document Number:

691201216

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: Graber, Candice (Nikki) On-Site Inspection 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 31257
 Name of Operator: FRITZLER RESOURCES INC
 Address: P O BOX 114
 City: FORT MORGAN State: CO Zip: 80701
Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|----------------|--------------------------|-----------------|
| Allison, Rick | | rick.allison@state.co.us | |
| Fritzler, Gene | (970) 867-9388 | gfritzler@bresnan.net | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 243352 | WELL | SI | 06/01/2017 | OW | 123-11143 | LAW 1-17 | EI |

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Inspected Facilities

Facility ID: 243352 Type: WELL API Number: 123-11143 Status: SI Insp. Status: EI

Environmental

Spill/Remediation:

Comment: COGCC personnel observed the partially buried produced water vessel had been removed from service and the excavation scar had been backfilled. As of the date of this inspection, Operator has not submitted a Form 27 for the removal of this vessel. Pursuant to Rule 905.b., Operator is required to close partially buried produced water vessels in accordance with prior approved Site Investigation and Remediation Workplan, Form 27.

Corrective Action: Operator shall submit an eForm 27, Site Investigation and Remediation Workplan, for the removal of the partially buried water vessel. The Workplan shall be submitted for prior COGCC approval and shall include a description of the proposed investigation and remediation activities in accordance with Rule 909.

Date: 02/26/2020

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------|---|
| 691201217 | Removed vessel | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5048657 |
| 691201218 | Backfilled Excavation | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5048658 |