

**Inspection Photos**  
**Operator: Catamount Energy**  
**Location/API #: 067-07911**  
**Date: 1-22-2020**



Photo 1. View of the project area from the southeastern corner facing center. Producing well in foreground is mapped on plugged well pad south of producing pad. Documentation needs to be fixed.



Photo 2. View of riser within the southern project area.



Photo 3. View of the eastern project area from the southeastern portion facing northward. Although snow covered, it is apparent that revegetation is progressing with grasses such as crested wheatgrass and western wheatgrass.