

Inspection Photos
Operator: Catamount Energy
Location/API #: 067-05455
Date: 1-22-2020



Photo 1. View of the project area from the northern edge facing southward. It appears that reclamation is initiated. Straw mulch observed beneath snow.



Photo 2. View of wattles placed along the western edge of the project area.



Photo 3. View of unused equipment that remains in the northwestern project area.



Photo 4. View of area beneath wattle that shows that wattle is not properly trenched within the soil.