

Inspection Photos
Operator: Catamount Energy
Location/API #: 067-09346
Date: 1-22-2020



Photo 1. View of the project area from the wellhead facing eastward.



Photo 2. View of unused equipment within the northwestern project area.



Photo 3. View of unused tank stored within the northwestern project area.



Photo 4. View of the northern project area from the northwestern edge facing eastward. Revegetation is progressing within the northern project area.



Photo 5. View of unused equipment stored within the eastern project area.



Photo 6. View of Russian thistle debris within the southern project area. Needs to be removed and properly disposed of.



Photo 7. View of bare soils within the southwestern project area. Erosion controls are needed to stabilize bare soils here.