

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/28/2020

Submitted Date:

01/28/2020

Document Number:

699500843**FIELD INSPECTION FORM**
 Loc ID 328359 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

| Contact Name | Phone | Email         | Comment                         |
|--------------|-------|---------------|---------------------------------|
| ,            |       | cogcc@kpk.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 248093      | WELL | PR     | 03/20/1995  | OW         | 123-15891 | SACK 44-31    | PR          |

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

|                    |              |       |  |
|--------------------|--------------|-------|--|
| Type               | PUMP JACK    |       |  |
| Comment:           | 4' barb wire |       |  |
| Corrective Action: |              | Date: |  |

**Equipment:**

|                           |                |       |                 |
|---------------------------|----------------|-------|-----------------|
| Type: Prime Mover         | # 1            |       | corrective date |
| Comment:                  | Electric motor |       |                 |
| Corrective Action:        |                | Date: |                 |
| Type: Pump Jack           | # 1            |       |                 |
| Comment:                  |                |       |                 |
| Corrective Action:        |                | Date: |                 |
| Type: Ancillary equipment | # 1            |       |                 |
| Comment:                  | electric       |       |                 |
| Corrective Action:        |                | Date: |                 |
| Type: Bradenhead          | # 1            |       |                 |
| Comment:                  |                |       |                 |
| Corrective Action:        |                | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

|                             |            |                       |            |                  |
|-----------------------------|------------|-----------------------|------------|------------------|
| <b>Inspected Facilities</b> |            |                       |            |                  |
| Facility ID: 248093         | Type: WELL | API Number: 123-15891 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>       |            |                       |            |                  |
| Comment:                    | PR         |                       |            |                  |
| Corrective Action:          |            |                       |            | Date:            |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment   | User    | Date       |
|---|---------|------------|
| At time of inspection location appears to be in compliance with COGCC rules.<br>At time of inspection perception of location may have been distorted due to weather conditions. | medinaj | 01/28/2020 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 699500844    | pics        | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5050160">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5050160</a> |