

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/22/2020

Submitted Date:

01/22/2020

Document Number:

693502112**FIELD INSPECTION FORM**Loc ID 318806 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	<a href="#">All inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242192	WELL	PR	03/20/1995	OW	123-09983	ROCKY MOUNTAIN FUEL CO C 8	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign not legible		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	02/22/2020

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds on well site and around equipment.		
Corrective Action:	Comply with rule 603f	Date:	01/29/2020

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Hog fence		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 242192 Type: WELL API Number: 123-09983 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR. At time of inspection flow lines off well head appear to be open. Electric panel is in the off position.

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary  On Wednesday January 22, 2020 at approximately 10:57AM, I, Inspector Randy Silver, conducted an on-site inspection.  Location: Rocky Mountain Fuel CO C #8  Operator: KP Kauffman  API#: 05-123-09983  County: Weld  While there, I observed a well site  During this inspection the following possible compliance issues were observed:  Weeds: Rule 603 f Corrective action date of 1-29-20 See photos 1,2,3  Sign: Rule 210 e Corrective action date of 2-22-20 See photo 2  Weather conditions: Cloudy and location dry  A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.  This is a summary of inspection report.</p>	silverr	01/22/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402292390	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5045159">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5045159</a>
693502113	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5045156">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5045156</a>