

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/21/2020

Submitted Date:

01/21/2020

Document Number:

699300947

**FIELD INSPECTION FORM**

Loc ID 331569 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263542	WELL	SI	10/01/2018	GW	123-20915	STREAR 1-15A	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained soil by Gas meter run flow lines		
Corrective Action:	Comply with Rule 1002..(2).D Conduct maintenance on equipment, cleanup stained material and review self inspection processes.	Date:	01/26/2020

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	AG fence X 2		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	AG fence		
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date	
Type: Horizontal Heated Separator	# 3				
Comment:					
Corrective Action:					Date:
Type: Bird Protectors	# 5				
Comment:					
Corrective Action:					Date:
Type: Bradenhead	# 1				
Comment:	Appears to be plumbed to surface				
Corrective Action:					Date:
Type: Gas Meter Run	# 4				
Comment:					
Corrective Action:					Date:
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:					Date:
Type: Bird Protectors	# 2				
Comment:					
Corrective Action:					Date:
Type: Emission Control Device	# 2				
Comment:					
Corrective Action:					Date:
Type: Ancillary equipment	# 8				
Comment:	Automation				
Corrective Action:					Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate				
Other (Content)					
Other (Capacity)	110 bbl				
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Shares containment with crude oil tank				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

**Inspected Facilities**Facility ID: 263542 Type: WELL API Number: 123-20915 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 1/21/2020 at approximately 0945 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location: Strear 1-15A at API #05-123-20915 in Weld County Colorado. While there, I observed a shut in wellsite &amp; tank battery. Report shows it as shut in since 10/2019.</p> <p>During this inspection the following compliance issue was observed: 1002..(2).D Housekeeping: stained soil by gas meter run flow line, CA date 1/26/2020. See attached photos 7 &amp; 8. Location is dry, weather cloudy.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	01/21/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402291544	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5044382">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5044382</a>
699300948	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5044377">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5044377</a>