

Inspection Photos
Location Name: ESTER (OWP) #1
API: 05-067-06232



PVC flowline located.



PVC flowline cut and capped.



Inspection Photos
Location Name: ESTER (OWP) #1
API: 05-067-06232



Trench backfilled.



Equipment mobilization.

