

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/27/2020

Submitted Date:

01/29/2020

Document Number:

690101700**FIELD INSPECTION FORM**Loc ID 320387 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10548Name of Operator: HRM RESOURCES II LLCAddress: 410 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		jeremy@p3petro.com	
Pape, Terry		tpape@hrmres.com	
		fbair@p3petro.com	
		jh@p3petro.com	
Whittington, Ellice		ellice.whittington@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Payne, Gina		gpayne@hrmres.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203625	WELL	PR	05/01/2019	OW	001-09185	KELTON A-3	EG

General Comment:

COGCC Engineering Integrity Inspection; Flowline Inspection Only. The Corrective Actions identified during this field inspection are located in the flowline section of report. Photos uploaded can be accessed via link(s) at end of report.

Inspected Facilities

Facility ID: 203625 Type: WELL API Number: 001-09185 Status: PR Insp. Status: EG

Flowline

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: Material:
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Producing Well.

The off location flowline(s) (KELTON A-3 wellhead flowline) run approximately 4560' SE from the wellhead to facility/ battery located at 39.891755, -104.564824. The actual alignment of off location flowline(s) is indeterminate at this time; Off location flowline(s) have not been registered with COGCC; Operator has not submitted COGCC Form 44.

Note: Operator has not registered any off location flowlines with COGCC; The Corrective Action outlined is applicable to all wells operated by HRM Resources II (Painted Pegasus Petroleum LLC) with off location flowlines.

Corrective Action: Comply with the following COGCC rule (partial description of rule):

1101.a. Off-Location Flowline Registration. (1) An operator must register an off-location flowline constructed on or after May 1, 2018, by submitting a Flowline Report, Form 44, to the Director within 30 days after the flowline is placed into service. An off location flowline in existence prior to May 1, 2018, must be registered by October 31, 2019.

Date: 10/31/2019

COGCC Comments

Comment	User	Date
ALL CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE	maclarej	01/29/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101707	Wellhead sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5051360
690101708	View SE from wellhead to facility/ battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5051361
690101709	Aerial Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5051362