

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/24/2020

Submitted Date:

01/29/2020

Document Number:

694600069**FIELD INSPECTION FORM**Loc ID 325354 Inspector Name: Duran, Alicia On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 5Name of Operator: COLORADO OIL & GAS CONSERVATIONAddress: 1120 LINCOLN ST SUITE 801City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Andrews, Dave		david.andrews@state.co.us	
Chollett, Shannon		shannon.chollett@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214628	WELL	SI	03/01/1993	GW	067-06232	ESTER (OWP) 1	PA

General Comment:

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

Emergency Contact Number:	
Comment:	<input type="text"/>
Corrective Action:	<input type="text"/>
Date:	_____

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PIT		
Comment:	Orange safety fence around open pit.		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 214628 Type: WELL API Number: 067-06232 Status: SI Insp. Status: PA

Flowline

#1	Type: Well Site	of Lines	
----	-----------------	----------	--

Flowline Description

Flowline Type: Well Site Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: 2" PVC flowline dug up and removed with an excavator to the edge of the pad site. Flowline cut and capped. Trench backfilled.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
1/23/2020 - Wellhead cut and plate marker welded on. PA completed.	durana	01/29/2020
1/24/2020 - PVC flowline cut and capped at the edge of pad site. Rig down moved out. All equipment mobilized off pad site.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694600070	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5051363