

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2020

Submitted Date:

01/30/2020

Document Number:

688800662**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Hughes, Jim _____ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	
Beebe, Sabre		sabre.beebe@bpx.com	All Inspections
Heil, John		john.heil@state.co.us	
Murray, Richard		g.richard.murray@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
470891	SPILL OR RELEASE	AC	01/22/2020		-	Robertson 19 1 1	EI

General Comment:

On January 30, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Spill/Release Point ID #470891. For more information regarding this release, please refer to document #402288080.

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 9

Comment: [Please refer to Spill/Release Point ID #470891 for more information regarding this release.](#)Corrective Action: [Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.](#)

Date: 02/28/2020

Reportable: YES

GPS: Lat 37.085601

Long -107.536948

Proximity to Surface Water: _____

Depth to Ground Water: 120

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Fail			Material Handling And Spill Prevention	Fail	

Comment: Excavated material does not appear to have any containment structures present.

Corrective Action: E&P waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 907. Contct COGCC EPS staff.

Date: 02/03/2020

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On January 30, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Spill/Release Point ID #470891. For more information regarding this release, please refer to document #402288080. During this inspection, a Crossfire construction crew and a BP representative were on site. The excavation was being backfilled, and reportedly some of the flow lines within the trench were to be abandoned. The operator shall submit any information that is available concerning failure analysis, integrity/pressure testing, and any data concerning the root causes of the spill. Provide all pipeline integrity data to the COGCC Western Integrity Inspector, Richard Murray, at (970) 989-3092 or g.richard.murray@state.co.us.	hughesjo	01/30/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800663	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5053927